

# **TECHNICAL BULLETIN**

S412-04

08/2002

Subject

#### **INACCURATE AMBIENT TEMPERATURES INDICATED IN LOW AMBIENTS**

Model: S-TYPE 4.2L Supercharged (North American Market Only)

Year: 2002.5 VIN M45945 to M61539

Section: 412 Climate Control System
Sub-Section: 412-04 Control Components

### Summary

Due to the position of the ambient temperature sensor and the influence of re-circulated air from the engine oil cooler, the ambient temperature sensor could be inaccurate up to 6 degrees Celsius, when the vehicle is operating in low ambient temperatures.

#### **Action**

The ambient temperature sensor requires repositioning to correct the reading from the sensor. On a customer complaint basis only, follow the workshop procedure outlined below.

## **Workshop Procedure**

- 1 Raise vehicle on four-post ramp.
- 2 Remove radiator splash shield (see Workshop Manual, JTIS CD ROM, section: 501-02).
- 3 Remove radiator lower cowl (see Fig. 1).




Fig. 1

- 4 Remove front bumper lower center vent trim.
- 5 Displace ambient temperature sensor from mounting clip (see Fig. 2).





Fig. 2

6 Displace ambient temperature sensor mounting clip from front bumper beam.




Front of vehicle
Existing mounting holes
Front bumper beam
Center line of vehicle

Fig. 3

# Note: Fig. 3 shows the front bumper beam viewed from the underside of the vehicle. All dimensions shown are in millimeters.

- 7 Mark position of new ambient temperature sensor mounting holes using dimensions shown in Fig. 3.
- 8 Center-punch marked position of new ambient temperature sensor holes.
- 9 Drill new ambient temperature sensor mounting holes 5mm and 6.5mm diameters in opposite orientation to existing holes (see Fig. 3).
- 10 Install ambient temperature sensor mounting clip to new mounting holes in opposite orientation.
- 11 Install ambient temperature sensor to mounting clip.
- 12 Install radiator lower cowl (see Fig. 4).



- Fig. 4
- 13 Install radiator splash shield (see Workshop Manual, JTIS CD ROM, section: 501-02).
- 14 Install front bumper lower center vent trim.
- 15 Lower vehicle on ramp.

# **Warranty Information**

Description	SRO	Labor Time Allowance	Warranty Code	Causal Part
Reposition ambient temperature sensor	82-91-27	0.5 Hours	JD FB 42	XR8 1509