

# Technical Service BulletinTechnical Service Bulletin

No.JTB00055 07 AugustAugust 2007

ReissueReissue

Please replace the previous edition of this bulletin. Please replace the previous edition of this bulletin.

This bulletin supersedes TSBThis bulletin supersedes

TSB A211-002v7/2006 dateddated 08 SeptemberSeptember, which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page). which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page).

This bulletin supersedes TSBThis bulletin supersedes

TSB B211-001v5/2006 dateddated 08 SeptemberSeptember, which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page).which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page).

This bulletin supersedes TSBThis bulletin supersedes

TSB S211-004v6/2006 dateddated 08 SeptemberSeptember, which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page).which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page).

Subject/ConcernSubject	Steering Gear Squeak
/Concern:	Steering Gear Squeak

ModelsModels:		
S-TYPE		VIN-rangerange: M45255 OnwardsOnwards
X-TYPE		VIN-rangerange: C00294 OnwardsOnwards
XJ Range		VIN-rangerange: G00442 OnwardsOnwards

MarketsMarkets: All SectionSection: 211-00

#### SummarySummary:

This bulletin addresses the possibility of a squeaking noise being emitted from the power steering system.

This version has been issued due to a change in the Labor Time and Service Instruction.

CauseCause: The power steering pinion seal lacks lubrication and dries out.

ActionAction: Should a customer express concern, add the specified fluid additive (see 'Parts

Required') to the power steering system and maneuver the steering wheel to lubricate the pinion seal. Follow the Service Instruction outlined below. Note

that this Bulletin is to fix 'squeaks' only.

Parts RequiredParts Required:				
DescriptionDescription	Part NumberPart Number	QuantityQuantity		
Fluid additive	C2S 48887	1		


Labour TimeLabour Time:				
Operation				
DescriptionOperation	Operation No.Operation No.	TimeTime		
Description				
Power Steering Squeaking Noise	F7 01 20/01	0.2 hours		
- Service Fix	07.91.29/01	0.2 hours		

Repair/Claim CodingRepair/Claim Coding:		
Causal	C2C 40007	
PartCausal Part:	C2S 48887	
ACES Condition		
CodeACES	42	
Condition Code:		
Defect		
CodeDefect Code:		


# Service InstructionService Instruction

**NOTENOTE:** This Service Instruction must be carried out in conjunction with SSM 34548, which contains a video clip showing the procedure.

- 11. Open driver door.
- 22 . Ensure the gear lever is in neutral/park, the parking brake is 'ON', and the ignition is 'OFF'.
- 33 . Open hood and install fender protectors.
- 44 . Remove the power steering fluid reservoir cap (and filter mesh on XJ and S-Type vehicles) and ensure the fluid level is correct.



- 55. Using a suitable clean syringe, remove 50ml of steering fluid.
- 66 . Replenish the power steering fluid reservoir with 50ml of the specified fluid additive. The fluid additive must only be added once, and the supplied label must then be affixed to the power steering reservoir to show that it has been added.
- 77 . **NOTENOTE:** Ensure suitable temperature reading equipment is positioned into the power steering fluid reservoir, (filter mesh must be removed on XJ and S-Type vehicles) and that the temperature can be read while carrying out the heating process.
  - Insert the temperature reading equipment probe into the power steering fluid reservoir (about halfway into the depth of the fluid).
- 88. Turn ignition 'ON' and start the engine.
- 99. With the engine idling, turn the steering wheel from end-lock to end-lock four times (to cycle the fluid additive into the system).



## Heating the steering fluid to 100±5°C

CAUTIONCAUTION: Under no circumstances turn the steering wheel to end-lock while heating the steering fluid (to avoid damage to the steering system).

CAUTIONCAUTION: While carrying out the following procedure, ensure that 105°C is not exceeded.

While stationary and with the steering wheel in the centre position (road wheels in the straight ahead position), turn the steering wheel 90° (quarter turn) right and hold firmly with both hands.

11 Increase the engine speed to 3000rpm.

22 Monitor the power steering fluid temperature until 100±5°C is reached.

B C 100 MIN

### Performing the steering manoeuver

**NOTENOTE:** The steering manoeuver should be carried out on a hard flat surface outside of the workshop.

1111


CAUTIONCAUTION: Do not hold the steering wheel on full lock for more than two seconds as this may cause damage to the steering system.

**NOTENOTE:** With the power steering fluid temperature at 100±5°C (with the engine set between minimum 900rpm and maximum 1000rpm).

Turn the steering wheel to full lock and hold for two seconds. Then from full lock turn the steering wheel quickly and rapidly back a quarter (90°) turn (refer to SSM 34548 which contains a video clip showing this procedure).

1212 Repeat step 11 eight times.

1313 Turn the steering wheel to the opposite lock, and repeat steps 11 and 12.



1414 Remove the temperature reading equipment from the power steering fluid reservoir.

1515 Install the power steering fluid reservoir cap, remove fender protectors, and close hood.

1616 **NOTENOTE:** If the vehicle continues to exhibit a squeak after the road test, carry out the 'Heating the steering fluid to  $100\pm5^{\circ}$ C' (Step 10) and 'Performing the steering manoeuver' (Steps 11, 12 & 13) to a maximum of two times. If further problems occur, contact Dealer Technical Support on (ROW) +44 1926 691738, (UK) 0870 8501666..

Road test the vehicle and check for a squeaking noise from the power steering system.

© 2007 Jaguar

4 of 4