PLS CHECK AND ADVISE DAYS AND IS NOW OFF.

CAUSE: 02 SENSOR FAILED

RN REFER TO TECH NOTES BELOW FOR REPAIR

DESCRIPTION

DD DD WU

1 C2D28856 SENSOR-OXYGEN

ARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE A: 21269 CHECK ENGINE LIGHT WAS NOT ON WHEN PULLING VEHICLE IN, CONNECTED VEHICLE TO SDD AND FOUND CODE P014A-00 OZ SENSOR DELAYED RESPONSE-RICH TO LEAN BANK 2 SENSOR 2. FOUND BULLETIN JTB00392NAS3, CORRESPONDING TO ISSUE AND CODES. REPLACED OZ SENSOR, UPDATED PCM CPLA-12B684-YF AND CLEARED CODES.

