



Sedan Range

DATE 7/96  
Amended 2/98

05.1-22

SERVICE

## TECHNICAL BULLETIN

MIL Illumination – DTC P0441 –  
Service Action S672

MODEL 1996 MY  
Sedan (4.0L) NA

VIN USA 772231-776270  
Can. 772231-784296

Remove and destroy Bulletin 05.1-22, dated 7/96.  
Replace with this Bulletin.  
Revised text is marked with a bar and in **bold text**.

### ISSUE:

Some 1996 MY Sedan Range vehicles within the above VIN ranges may experience illumination of the Malfunction Indicator Lamp (MIL) caused by DTC P0441 being falsely registered in the Engine Control Module (ECM).

On US market Sedan Range vehicles, the condition could occur on Vanden Plas (long wheelbase) vehicles **only**. On Canadian market Sedan Range vehicles, it can occur on **both** XJ6 and Vanden Plas (short wheelbase and long wheelbase) vehicles.

This condition can be rectified by replacing both of the Programmable Read Only Memories (PROMs) with new PROMs from the appropriate modification kit.

### ACTION:

Refer to **Technical Bulletin 05.1-25, dated 4/97**. The software revisions for Service Action S672 to solve the above complaint were incorporated in the PROMs designed for Service Action S676.