










Unrelated Events (Distance)

events.session.vin: SAJAC73R15TG35785
 events.session.created: Wed 02-Jan-2013 22:34
 events.session.printed: Thu 03-Jan-2013 02:09



DTC	ECU	Distance	Description	Status	Options	Relevance
Unknown Events						
C1419	ASU	-----km	Front right damper - circuit open			0%
B1895	DDM	-----km	Driver's/passenger's door ajar output - circuit failure			0%
B1940	DSM	-----km	Seat memory position out of range			0%
P1111	ECM	-----km	System check complete			0%
P1582	ECM	-----km	Throttle monitor data available			0%
P0480	ECM	-----km	Radiator fan slow			0%
P1260	ECM	-----km	Security input			0%
B2319	FEM	-----km	No description available			0%
B2496	FEM	-----km	Anti-theft horn circuit - short to ground			0%
Untested DTCs: <input type="radio"/> Show <input checked="" type="radio"/> Hide On demand self-test DTCs: <input type="radio"/> Show <input checked="" type="radio"/> Hide						
B1987	FEM	-----km	Pedal forward/rearward motor stalled			0%
XJ (X350) G35785 - 03 Jan 2013 02:09 (DVD130.07 v.135) The Mongoose JLR is connected.						
C1755	FEM	-----km	Right seat heater power shutdown			0%
B1222	FEM	-----km	Master Lock/Unlock Switch			0%
B1601	IP	-----km	Passive anti-theft system received incorrect key code from ignition key transponder			0%
U1900	IP	-----km	CAN communications bus fault			0%
U2510	IP	-----km	CAN - invalid data for vehicle security			0%
U2195	IP	-----km	SCP (J1850) invalid data from the steering column lock control module			0%
U2150	IP	-----km	SCP (J1850) invalid data from the rear electronics control module			0%
U2152	IP	-----km	SCP (J1850) invalid data from the general electronics control module			0%
U1262	IP	-----km	SCP (J1850) Communications bus fault			0%
C1986	IP	-----km	Variable assist power steering initial speed is above threshold			0%
B2139	IP	-----km	Data mismatch (received data does not match expected data)			0%
U1262	REM	-----km	SCP (J1850) Communications bus fault			0%

B2162	REM	-----km	Right side module invalid identification		0%
P1235	REM	-----km	Fuel pump control out of range		0%
B2533	REM	-----km	Rear right stoplamp - circuit failure		0%
B2565	REM	-----km	Right tail lamp - circuit failure		0%
B2577	REM	-----km	Left tail lamp circuit failure		0%
U3FF6	REM	-----km	No description available		0%