

Sedan Range

DATE 11/95

15-33

SERVICE

TECHNICAL BULLETIN

Oil Pressure Gauge – Modification Procedure – Unsold Vehicles – Service Action S657 MODEL 1995 MY Sedan Range VIN

720001-746613

ISSUE:

Technical Bulletin 15-13, Dated 6/95 detailed a modification procedure for customer concerns of low or fluctuating oil pressure on 1995 MY Sedan Range vehicles within the above VIN range.

In order to eliminate the possibility of similar complaints by future customers, all unsold stock of the above vehicles should also be modified.

ACTION:

Replace the oil pressure transducer with an oil pressure switch on all unsold stock 1995 MY Sedan Range vehicles within the above VIN Range. Whenever possible, this procedure should be performed when the vehicle is undergoing PDI. Vehicles that have already been prepared for sale should be modified before delivery to the customer.

Refer to Technical Bulletin 15-13, Dated 6/95 for the modification procedure.



PARTS INFORMATION:

DESCRIPTIONPART NUMBERQTYOil pressure switchLNA 5642CA1

WARRANTY INFORMATION:

Service Action S657

VEHICLE	SUMMARY CODE	DESCRIPTION	TIME ALLOWANCE
XJ6 1995 MY VIN 720001-746613 Model codes 2310 2311, 2313, 2314	KG	Remove transducer, install oil pressure switch and re-calibrate instrument pack -without drive-in/out time (performed at PDI)	0.30 hrs.
XJ12 1995 MY VIN 720001-746613 Model code 2512			0.15 hrs.
XJ6 1995 MY VIN 720001-746613 Model codes 2310 2311, 2313, 2314	КН	Remove transducer, install oil pressure switch and re-calibrate instrument pack -with drive-in/out time (performed after PDI, prior to retail)	0.45 hrs.
XJ12 1995 MY VIN 720001-746613 Model code 2512			0.30 hrs.

CLAIM SUBMISSION PROCEDURE:

Warranty summary codes have been assigned to this service action in order to simplify claim submission. The dealership will be reimbursed the parts and labor time allowance as indicated.

DCS DEALERS

Submit claims using the appropriate summary code for the vehicle model and work performed. Follow standard campaign submission procedures.

NON-DCS DEALERS

Submit claims on the Recall Campaign Summary form W-25. Enter the appropriate summary code for the vehicle model and work performed in the Repair Code column. Do not use the W-1 warranty claim form.

