

Models	X150 - XK (Coupe) X150 - XK (Convertible) X250 - XF
--------	---

Title	Loose battery terminals
-------	-------------------------

Last Modified	16-JUL-2008 16:19
---------------	-------------------

Category	Electrical
----------	------------

Symptom	203000 Basic Electrical
---------	-------------------------

Issue

A number of reports have been received where the battery terminal has come adrift causing significant electrical concerns.

Cause

The battery terminal has been incorrectly fitted during the PDI process or whilst the vehicle is in the workshop for repair.

Action

Ensure that the battery terminal is located correctly as shown in the attached document. The battery post should protrude through the clamp and then be torque tightened to 6 Nm for XF or 5 Nm for XK variants.

Continued below ----

Battery terminal – correct fitting.

