501-SEATING

ISSUE: S501-08 - REMOVAL AND INSTALLATION PROCEDURE – FRONT SEAT BACK COVERS

This Technical Bulletin has been raised to supply information to Dealers when removing/installing the front seat back covers on S-TYPE vehicles.

It has been discovered that when Dealer Technicians are removing/installing the front seat back covers, sometimes the fixings are broken and are not always replaced.

ACTION

When removing/installing the front seat back covers (see Workshop Manual, JTIS CD ROM, section 501-10), Dealer Technicians should take great care not to break any of the fixings. To prevent the fixings being broken during the removal, the fixings should be carefully prized apart using a suitable flat blade trim tool, whilst fully supporting the weight of the seat back cover.

If any of the fixings are broken, they should be replaced. If a fixing/retention point on the seat back cover is broken, the complete seat back cover should be replaced.

See Workshop Manual, JTIS CD ROM, section 501-10 for fixing/retention points.

PARTS INFORMATION

Description	Part Number	VIN Range	Quantity
Fir tree fixing	XR8 23622	All	4
Seat back cover*	XR8 11043	Prior to L70000	1
Seat back cover*	XR8 21792	Post L70000	1

*These seat back covers are not handed and part numbers should be suffixed with a color code.

This Technical Bulletin is for information only.