

SENDING UNIT RESISTANCE LEVELS - XJ6

Tank Contents	Gauge Indication	Approximate Resistance (ohms)
Dry to 1.6 gal. (6 liters)	Empty	900
2.6 gal. (10 liters)	Low Fuel Lamp on/off	735
5.3 gal. (20 liters)	1/4	560
10.6 gal. (40 liters)	1/2	360
15.9 gal. (60 liters)	3/4	195
21.1 gal. (80 liters)	Full	80

SENDING UNIT RESISTANCE LEVELS - XJS

LEVEL	RE5ISTANCE(Ohms)
Empty	24O - 25O
Warning Light	185 - 215
1/4	102 - 104
1/2	68-70
3/4	44-46
Full	16-18