

ABS - C1295 STEERING WHEEL ANGLE SENSOR - IMPLausible FAULT
C1236 REAR LEFT WHEEL SPEED SENSOR COMPARISON FAULT

ECM (ENGINE) P0037 HEATED OXYGEN SENSOR HEATER CONTROL CIRCUIT LOW (BANK 1 SENSOR 2)
P0057 → SAME (BANK 2 SENSOR 2)

SAME - * P0701 COMBINATION OF IMPOSSIBLE SUBSTITUTE FUNCTIONS.

WILL NOT DELETE → C1175 WHEEL SPEED REAR LEFT INPUT - CIRCUIT FAILURE
P1582 FLIGHT RECORDER DATA IS STORED.
P1632 GENERATOR CHARGE SYSTEM FAILURE / GENERATOR 'LOAD' FEEDBACK CIRCUIT FAILURE
P1000 SYSTEM CHECK NOT COMPLETED SINCE LAST MEMORY CLEAR

T.C.M (TRANS)

P0706 TRANSMISSION RANGE SENSOR CIRCUIT RANGE OR PERFORMANCE
P0730 INCORRECT GEAR RATIO
P0720 OUTPUT SPEED SENSOR CIRCUIT MALFUNCTION
P1799 CAN TRANSMISSION CONTROL MODULE / ABS CONTROL MODULE CIRCUIT MALFUNCTION

SAME * P0701

DRIVERS DOOR MODULE - B1234, B2322, B2323
PASSENGER DOOR MODULE FAULTS WITH MIRROR

B.P.M. BODY PROCESSOR MODULE

B2334 COLUMN DRIVE, TILT OUT OF RANGE HIGH
U1041 VEHICLE SPEED NOT OBTAINED.
U2012 COMMUNICATION BUS ERROR - NON SCP.
B1545 IGNITION SWITCH - ILLEGAL INPUT CODE

SLM - SECURITY LOCKING MODULE

B1232 INCLINATION SENSOR SELF CHECK FAIL,
U1135 IGNITION STATES NOT OBTAINED.
U1041 VEHICLE SPEED NOT OBTAINED.

PASSENGER SEAT 1 CODE
 PAS " HEAD RESTRAINT 1 CODE
 DRIVER " " 1 CODE
 LEFT LIGHTING MODULE 2 CODES
 RIGHT " " 2 CODES
 ADRC - ADAPTIVE DRIVING
 MODE CONTROL C1516 5 VOLTS SUPPLY -
 CIRCUIT SHUNT TO BATTERY

ATC - CLIMATE CONTROL B1250 IN CAR TEMP. SENSOR CIRCUIT
 B1853 " " " " MOTOR
 - CIRCUIT FAILURE
