

Portable Diagnostic Unit –  
XK8 Misfire Detection – Reprogramming

MODEL 1997 MY  
XK8 Range  
VIN 001001-018107

**ISSUE:**

The XK8 Misfire Detection reprogramming software has been issued for the Portable Diagnostic Unit. The CD-ROM is used when performing Service Action 819.

**ACTION:**

Refer to Technical Bulletin 303-23, dated 1/98. The procedures must be followed exactly to prevent damage to the ECM.



ILLUSTRATION 1