



All

DATE 11/04

X-30

PARTS

INFORMATION BULLETIN

Accessory CD Changer Installation –
2004 MY-ON XJ range

MODEL 2004 MY-ON
XJ range
VIN

Issue:

The installation of an accessory CD changer on 2004 MY-ON XJ vehicles requires the following part numbers:

Description:

Part No.

- CD Autochanger C2S17222
- Installation Kit C2C 12330
- D2B Fiber Optic Link Lead (1) Various – See matrix on the next page

Notes:

(1) Part No. is subject to vehicle specification – see matrix on the next page



XJ D2B Link Lead Matrix

To select correct Telematics link lead from the matrix below please read the following;

- 1) Select the final specification of vehicle once upgraded (including existing features)
- 2) Select link lead part number from the matrix below for final specification of vehicle.

Please note only 1 link lead is required for any upgrade.

		Final vehicle specification post upgrade																				
		Link Lead Part No.	C2C 14149	C2C 14156	C2C 14148	C2C 14157	C2C 14150	C2C 14147	C2C 14151	C2C 14162	C2C 14171	C2C 14165	C2C 14173	C2C 14164	C2C 14172	C2C 14163	C2C 14153	C2C 14154	C2C 14155	C2C 14168	C2C 14169	C2C 14170
Vehicle specification post retrofit	CD A/CHANGER	X		X		X		X	X		X		X		X	X	X	X	X	X	X	X
	TELEPHONE		X	X			X	X		X	X				X	X	X		X	X		X
	VOICE				X	X	X	X					X	X	X	X		X	X		X	X
	NAVIGATION									X	X	X	X	X	X	X				X	X	X
	PREMIUM ICE																X	X	X	X	X	X



= FACTORY FIT OPTION ONLY



= DLR INSTALLED ACCESSORIES

Example: Link lead required for vehicle with existing CD, upgrading vehicle to include telephone.

Final vehicle specification = CD and Telephone, Therefore Telematics link part number required will be 14148