

2016.0 XE (X760), 501-05

INTERIOR TRIM AND ORNAMENTATION

SUN VISOR_[G1823598]

REMOVAL AND INSTALLATION

76.10.48	ILLUMINATED SUN VISOR ASSEMBLY - RENEW	ALL DERIVATIVES	0.1	USED WITHINS	+
----------	--	-----------------	-----	--------------	---

REMOVAL


NOTE:

Removal steps in this procedure may contain installation details.

1.

CAUTION:


Use a suitable trim tool.



2.

NOTE:

Repeat the step for the other side.



E173999

TORQUE: 4.1 Nm

INSTALLATION

1. To install, reverse the removal procedure.

