

Events by distance



VIN: SALVA2AG4HH216241
 Model: Land Rover L538 Evoque
 Session creation: Mon 04-Dec-2017 13:16
 Session printed: Mon 04-Dec-2017 13:30
 Current odometer: 12km



DTC	ECU	Distance ▼	Description	Status	Options	Relevance
Unknown Events						
U3001-00	PSCM	-----km	Control Module Improper Shutdown - No sub type information			
Untested DTCs						
U3003-16	ABS	-----km	Battery voltage			
U3003-17	ABS	-----km	Battery voltage			
P1707-74	TCM	-----km	J_14229_DTC_P1707			
DTCs No Longer Reported						
B1111-77	ABS	-----km	Electronic park brake Enable - Commanded position not reachable			
U2002-92	ABS	-----km	Switch - Performance or incorrect operation			
U0001-87	AWDCM	-----km	High speed CAN communication bus - Missing message			
U0300-46	GWM	-----km	Internal control module software incompatibility - Calibration / parameter memory failure			
B1B72-11	HVAC	-----km	Stepper motor actuator LIN Bus power supply - Short to ground			
U0028-87	IPC	-----km	Vehicle Communication Bus A - Missing message			
U0001-87	IPMB	-----km	High speed CAN communication bus - Missing message			
U3000-46	IPMB	-----km	Control module - Calibration/parameter memory failure			
P0113-00	PCM	-----km	Intake air temperature sensor 1 circuit high (bank 1) - No sub type information			
P2162-26	PCM	-----km	Vehicle Speed Sensor A / B Correlation - Signal rate of change below threshold			
U0101-00	PCM	-----km	Lost communication with the TCM - No sub type information			
P0850-29	TCM	-----km	Park/neutral Switch Input Circuit - Signal invalid			
P1707-72	TCM	-----km	Transfer Case Neutral or Park/Neutral Indication Circuit - Actuator stuck open			
ECUs Not Responding						
	VIM					