

CUSTOMER #:



INVOICE

JAGUAR HOUSTON NORTH
LAND ROVER HOUSTON NORTH
18205 I-45 North
Houston, TX 77090
(832) 249-2000
Fax (832) 249-2069

PAGE 1

Form with fields: BUS, CELL, SERVICE ADVISOR, COLOR, YEAR, MAKE/MODEL, VIN, LICENSE, MILEAGE IN / OUT, TAG, DEL. DATE, PROD. DATE, WARR. EXP., PROMISED, PO NO., RATE, PAYMENT, INV. DATE, R.O. OPENED, READY, OPTIONS: STK:SAMR70063 TRN:Automatic_LHS

Table with columns: LINE OPCODE, TECH, TYPE, HOURS, LIST, NET, TOTAL. Row 1: A CUSTOMER REQUESTED A LOAN LOAN LOANER, 4376 CC 0.00, 0.00, 0.00, 0.00, 0.00, 0.00

B CLIENT STATES REAR WINDOWS WILL ROLL BACK DOWN AFTER ROLLING UP CAUSE: RECALL 869408 CONFIGURE DRIVERS AND PASSENGERS DOOR MODULES AND INITIALISE WINDOWS 4376 WC 0.50 PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE B: 0.00 (N/C)

28046 FOUND BOTH REAR WINDOWS TO ROLL BACK WHEN ON AUTO UP. REFERED TO K061 AND REFLASHED BOTH FRONT DOOR MODULES C CLIENT STATES WHEN ACCEL ON FULL THROTTLE THE VEHICLE HAS A TICKING NOISE CAUSE: BULLETIN JTB00241NAS1 195021 FUEL INJECTION COMPONENT CLEANING USING PRESSURE CLEANER - VIA AIR INTAKE 4376 WC 0.70 1 BG44K/BG 44K FUEL ADDITIVE 1 BG206/AIR INTAKE CLEANER PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE C: 0.00 (N/C)

28046 TEST DROVE VEHICLE AND FOUND ENGINE TO PING ON ACCEL. PERFORMED BULLETIN JTB00241NAS1 AND BG FUEL SYSTEM CLEAN.

D *Recommended Package *Change Engine Oil & Oil Filter *Brake Inspection includes Complimentary Tire Rotation *Reset Tire Pressures Top Up Fluids As Needed *Replace Dual Engine Air Filter *Replace Cabin Air Filter *Balance Four Tires Upgrade *Replace Front Wiper Blades *zMAX Micro Lubricant 32ozReduce

Table with columns: NO REFUND ON SPECIAL ORDER PARTS, STATEMENT OF DISCLAIMER, DESCRIPTION, TOTALS. Rows include: LABOR AMOUNT, PARTS AMOUNT, GAS, OIL, LUBE, SUBLET AMOUNT, MISC. CHARGES, TOTAL CHARGES, LESS INSURANCE, SALES TAX, PLEASE PAY THIS AMOUNT