

PUBLISHED: 11-MAY-2011  
2012.0 XF (X250), 501-12

## INSTRUMENT PANEL AND CONSOLE OVERHEAD CONSOLE [G1061424]

### REMOVAL AND INSTALLATION

---

76.13.69	ROOF CONSOLE - RENEW	ALL DERIVATIVES	0.20	USED WITHINS	+
----------	----------------------------	--------------------	------	--------------	---

---

### REMOVAL


**NOTE:**

Removal steps in this procedure may contain installation details.


1.

**CAUTION:**

Take extra care not to damage the edges of the component.



2.




E99884

3.

**NOTE:**

Do not disassemble further if the component is removed for access only.




E99885

4.

**CAUTION:**


Take extra care not to damage the wiring harnesses.



E99886

- Take precautions to avoid any electrostatic charging, which could damage this component.


5.





6.

**CAUTION:**

Take extra care not to damage the wiring harnesses.





7.



E99889

8.



E99890

