

LEAKING COOLANT. REMOVE SUPER CHARGER AND REVERSE COLLECT TEST THE
 PIPE. VACUUM FILL COOLING SYSTEM AND TEST FOR ANY OTHER LEAKS. 4.4h

D CUSTOMER STATES A/C BLOWS HUMID AIR ON STARTUP AND TAKES A LONG COOL
 CAUSE: F

700 *****A/C & HEATING REPAIR*****

345 WWPJ 1.80

1 C2D42376 KIT-AIR CONDITIO

2 R134 R134 FREON

78935 test drove and found ac system to have weak performance.,
 inspected and found charge level good. direct pressure sensing valve

(N/C)

(N/C)

(N/C)

NO CLAIMS WITHOUT THIS INVOICE SHOP SALES	PARTS SALES	DESCRIPTION	TOTALS
ALL LABOR IS WARRANTED FOR 90 DAYS OR 4000 MILES WHICHEVER OCCURS FIRST.	ALL PARTS SOLD OR USED ARE SUBJECT TO THE MAGNUSON-MOSS ACT AND THE MERCHANDISE PURCHASED IS UNDER LIMITED WARRANTY BY THE MANUFACTURER. THE TERMS OF THESE WARRANTIES ARE AVAILBLE FOR YOUR INSPECTION.	LABOR AMOUNT	
		PARTS AMOUNT	
		GAS, OIL, LUBE	
		SUBLET AMOUNT	
		OTHER LABOR & MATERIALS	
		TOTAL CHARGES	
		LESS INSURANCE/DISCOUNTS	
		SALES TAX	
CUSTOMER SIGNATURE	PLEASE PAY THIS AMOUNT		