



NOTE: WHEN THE IGNITION SWITCHED GROUND INPUT IS INTERRUPTED DURING ENGINE CRANKING THE ACCM DOES NOT DRIVE HIGH POWER CONSUMING COMPONENTS.