



All

DATE 02/02
Amended 08/02

7-20

SERVICE

ADMINISTRATION BULLETIN

Recall T493 - 1995 MY/Recall R493 - 1996-97
MY – AJ16 EGR System –
Replace PROMs and EGR Valve

MODEL
1995-96 MY XJS (4.0L)
1995-97 MY Sedan (4.0L)
VIN
194775-226645
720120-812255

Remove and destroy Bulletin 7-20 dated 02/02.
Replace with this Bulletin.
This Bulletin also supersedes Bulletin 7-19, amended 11/01.

Note: In January 2002 Jaguar advised you that the above recall action required on 1995 MY vehicles was temporarily suspended due to unforeseen problems with one of the components associated with this recall. Jaguar had requested that dealers cease conducting further actions on 1995 MY vehicles until the problem with the affected component had been resolved.

Jaguar is now pleased to inform you that the issue with the PROMs has been resolved, and that Jaguar once again will be contacting owners requesting that they contact their dealer to have the repair performed.

This version of the recall bulletin has revised part numbers for the 1995 MY vehicles. Additional Warranty Information has been added for those 1995 MY vehicles previously re-worked under this Recall Action. Please destroy all previous versions of Recall Action Bulletin R493 and replace it with this version.

Please note that the Recall number for all 1995 MY vehicles is now T493, R493 will continue to be used for 1996-97 MY vehicles.

ISSUE:

Refer to this bulletin for the Warranty Information for T493 and R493.

1995-97 XJ6 AND XJR VEHICLES

Refer to Technical Bulletin 05.1-26 Amended 08/02 for procedures to repair 1995-97 XJ6 and XJR vehicles.

1995-96 XJS 4.0L VEHICLES

Refer to Technical bulletin 17-12 Amended 08/02 for procedures to repair 1995-96 XJS 4.0L vehicles.

WARRANTY INFORMATION:

Warranty claims should be submitted quoting the information found in the table below. This will result in payment of the stated time and, where applicable parts/ miscellaneous expense codes as listed.

Drive in/drive out may only be claimed when the vehicle has been brought in for this action alone to be undertaken.

Please use option code of X and **also enter** the SRO (s) and parts details on the claim applicable to the repair completed.

Recall T493 - 1995 MY XJS 4.0L

VIN SC194775 - SC222631

REPLACEMENT OF PROMS IN ECM

Vehicle	Repair	SRO	Time	Part Number	Description	QTY
XJS 4.0 VIN Range: 194775 - 222631	Replace PROMS within ECM	18.91.18	0.7	LNC 1411BB	PROM Kit	1

EGR VALVE & GASKET REPLACEMENT

XJS 4.0 VIN Range: 194775 - 195695	Replace EGR valve & gasket	17.45.01	0.2	LHE 1550BA C2A 1231 FS 108251J	EGR valve Gasket Set screw	1 1 As Req.
---------------------------------------	----------------------------	----------	-----	--------------------------------------	----------------------------------	-------------------

THROTTLE RETURN SPRING REPLACEMENT

XJS 4.0 VIN Range: 194775 - 226645	Replace throttle return spring	19.91.46	0.2	NBB 3131AB	Throttle return spring	1
---------------------------------------	--------------------------------	----------	-----	------------	------------------------	---

DRIVE IN/DRIVE OUT

ALL	Drive in/drive out	10.10.10	0.1			
-----	--------------------	----------	-----	--	--	--

Recall R493 - 1996 MY XJS 4.0L

VIN TC222632 - TC226645

REPLACEMENT OF PROMS IN ECM

Vehicle	Repair	SRO	Time	Part Number	Description	QTY
XJS 4.0 VIN Range: 222632 - 226645	Replace PROMS within ECM	18.91.18	0.7	LNC 1411FA	PROM Kit	1

EGR VALVE & GASKET REPLACEMENT

XJS 4.0 VIN Range: 195696 - 226645	Replace EGR valve & gasket	17.45.01	0.2	LHE 1550AC C2A 1231 FS 108251J	EGR valve Gasket Set Screw	1 1 As Req.
---------------------------------------	----------------------------	----------	-----	--------------------------------------	----------------------------------	-------------------

THROTTLE RETURN SPRING REPLACEMENT

XJS 4.0 VIN Range: 194775 - 226645	Replace throttle return spring	19.91.46	0.2	NBB 3131AB	Throttle return spring	1
---------------------------------------	--------------------------------	----------	-----	------------	------------------------	---

DRIVE IN/DRIVE OUT

ALL	Drive in/drive out	10.10.10	0.1			
-----	--------------------	----------	-----	--	--	--

Recall **T493** 1995 MY XJ6 Normally Aspirated Vehicles Only

VIN SC720120 - SC754303

REPLACEMENT OF PROMS IN ECM

Vehicle	Repair	SRO	Time	Part Number	Description	QTY
95 MY XJ6 VIN Range: 720120 - 754303	Replace PROMS within ECM	18.91.18	0.7	LNC 1411AB	PROM Kit	1

EGR VALVE & GASKET REPLACEMENT

95 MY XJ6 VIN Range: 720120 - 754303	Replace EGR valve & gasket	17.45.01	0.2	LHE 1550AC C2A 1231 FS 108251J	EGR valve Gasket Set Screw	1 1 As Req.
---	----------------------------	----------	-----	--------------------------------------	----------------------------------	-------------------

THROTTLE RETURN SPRING REPLACEMENT

95 MY XJ6 4.0 NA VIN Range: 720120 - 754303	Replace throttle return spring	19.91.46	0.2	NBB 3131AB	Throttle return spring	1
--	--------------------------------	----------	-----	------------	---------------------------	---

DRIVE IN/DRIVE OUT

ALL	Drive in/drive out	10.10.10	0.1			
-----	--------------------	----------	-----	--	--	--

Recall **T493** 1995 MY XJR Supercharged Vehicles Only

VIN SC720120 - SC754303

THROTTLE RETURN SPRING REPLACEMENT

95 MY XJR VIN Range: 720120 - 754303	Replace throttle return spring	19.91.46	0.6	NBB 3131AB	Throttle return spring	1
---	--------------------------------	----------	-----	------------	---------------------------	---

DRIVE IN/DRIVE OUT

ALL	Drive in/drive out	10.10.10	0.1			
-----	--------------------	----------	-----	--	--	--

Recall R493 1996-97 MY XJ6 Vehicles Only

VIN TC754304 - TC787953 (1996 MY)

VIN VC787954 - VC812255 (1997 MY)

REPLACEMENT OF PROMS IN ECM

Vehicle	Repair	SRO	Time	Part Number	Description	QTY
96 MY XJ6 SWB VIN Range: 754304 - 787953	Replace PROMS within ECM	18.91.18	0.7	LNC 1411CA	PROM Kit	1
96 MY XJ6 LWB VIN Range 754304 - 787953	Replace PROMS Within ECM	18.91.18	0.7	LNC 1411DA	PROM Kit	1
96 MY XJR VIN Range 754304 - 787953	Replace PROMS within ECM	18.91.18	0.7	LNC 1411EA	PROM Kit	1
97 MY XJ6 SWB VIN Range: 787954 - 812255	Replace PROMS within ECM	18.91.18	0.7	LNC 1411GA	PROM Kit	1
97 MY XJ6 LWB VIN Range 787954 - 812255	Replace PROMS within ECM	18.91.18	0.7	LNC 1411HA	PROM Kit	1
97 MY XJR VIN Range 787954 - 812255	Replace PROMS Within ECM	18.91.18	0.7	LNC 1411JA	PROM Kit	1

EGR VALVE & GASKET REPLACEMENT

XJ6 VIN Range 754304 - 812255	Replace EGR valve & gasket	17.45.01	0.2	LHE 1550AC C2A 1231 FS 108251J	EGR valve Gasket Set Screw	1 1 As Req.
----------------------------------	----------------------------	----------	-----	--------------------------------------	----------------------------------	-------------------

THROTTLE RETURN SPRING REPLACEMENT

XJ6 4.0 NA VIN Range: 754304 - 812255	Replace throttle return spring	19.91.46	0.2	NBB 3131AB	Throttle return spring	1
XJR VIN Range 754304 - 812255	Replace throttle return spring	19.91.46	0.6	NBB 3131AB	Throttle return spring	1

DRIVE IN/DRIVE OUT

ALL	Drive in/drive out	10.10.10	0.1			
-----	--------------------	----------	-----	--	--	--