
2002 XJ RANGE - Instrument Panel and Console - 501-12

Instrument Cluster Finish Panel 76.47.24

Removal

- 1. Turn ignition key to position II.
- 2. Move steering column to lowest and fully extended position.
- 3. Turn ignition key to position 'O'.
- 4. Remove battery cover and disconnect ground cable from battery terminal. Refer to <<86.15.15>>.



E36343

- 5. Release veneer panel from retaining clips.
- 6. Remove veneer panel from vehicle.
- 7. Remove and discard all retaining clips.

Installation

- 1. Fit new retaining clips to instrument surround.
- 2. Fit and fully seat veneer panel to instrument surround.
- 3. Connect ground cable to battery terminal and fit battery cover. Refer to <<86.15.15>>.

1

2011-07-15

2002 XJ RANGE - Instrument Panel and Console - 501-12

- 4. Turn ignition key to position II.
- 5. Return steering column to original position.
- 6. Turn ignition key to position 'O'.

2 2011-07-15