
1998 XJ RANGE - Intake Air Distribution and Filtering - 303-12


Supercharger Outlet Pipe 18.50.16

Removal

- 1. Remove air cleaner cover / intake assembly; refer to 19.10.30.
- 2. Drain radiator coolant; refer to operation (SC) 26.10.01.




- 3. Disconnect coolant hoses and vacuum pipe from supercharger outlet duct.
 - Place absorbent rags under the two coolant hoses which are connected to the outlet duct.
 - 1. Remove vacuum pipe.
 - 2. Disconnect hoses.
 - Plug hoses and outlet duct stub pipes to prevent spillage.



Remove supercharger outlet duct.

- 1. Remove three bolts.
- 2. Remove four bolts.
- Discard rubber seals from bolts. 3. Remove outlet duct.
- Discard outlet duct gasket.

5. Blank supercharger outlet with body tape, or similar, to prevent ingress of foreign matter.




- 1. Remove two clamp plates.
 - 2. Discard two ducts.
- 8. Clean all relevant parts and mating faces.


1998 XJ RANGE - Intake Air Distribution and Filtering - 303-12

Installation

- 1. Re-assemble charge air cooler clamp inlet assembly.
 - Use new ducts.




2. Install charge air cooler inlet assembly to charge air coolers.




E32976 3. CAUTION: Take care to avoid ingress of dirt or foreign matter into the supercharger.

Install supercharger outlet duct.

- 1. Remove blanking tape from outlet port of supercharger.
- Clean supercharger outlet mating face.
 - 2. Install new gasket.
 - 3. Install duct.
 - 4. Install new rubber seals to the four bolts.



Secure charge air cooler inlet assembly to supercharger outlet duct.
Install bolts.



- 2. Install coolant hoses.
- 6. Refill cooling system; refer to (SC) (26.10.01).
- 7. Install intake tube / air flow meter / air cleaner cover assembly; refer to 19.10.30.