## www.jagrepair.com



Top View of Throttle Body



Side view of plugs



Found that the plug stays were broken



With intake removed



Readjust plug connectors



Another view

## These photos were supplied from Jaguar Forum member Gus and were copied from his website: **www.jagrepair.com**





Mirror view

