

Blocked air filter

Fuel system return blockage

Leaking fuel injector(s)

Fuel pressure regulator failure (high fuel pressure)

ECM receiving incorrect signal from one or more of the following components:
ECTS, MAFS, IATS, TPS