



Shop Name: --  
 Tel: --  
 Email: --  
 Address: --

Report ID: MAXIA20250730010738  
 Test Time: 2025-07-30 01:07:38  
 Technician: --

# 1998 Jaguar Vehicle Diagnostic Report

## Vehicle Information

1998/Jaguar/X300/BASE  
 VIN: SAJKX6248WC831715

Odometer Reading: 70200miles

License Plate: JAGUAR 1

## Customer Information

Name: --















Tel: --

## Device information

Scanner: MaxiCOM MK808Z  
 Version: V1.70

Serial Number: DK1GP9C04107  
 Repair Order Number:  
 DK1GP9C0410720250730010445490

## System Scanned ( 14 )

System	Status/DTC
ECM	 1
TCM (Transmission Control Module (TCM))	 1
ABS	 0
IPK (Instrument Pack)	 2
CCM (Climate Control Module)	 3
DDM (Driver Door Module)	 0
PDM (Passenger Door Module)	 0
DSM (Driver Seat Module)	 0
PSM (Passenger Seat Module)	 0
DRDM (Driver's (Side) Rear Door Module)	 0
PRDM (Passenger's (Side) Rear Door Module)	 0
SLM (Security Locking Module)	 0
BPM (Body Processor Module)	 0
ACM (Restraints Control Module (RCM))	 0

## DTC ( 7 )

### ECM ( 1 DTC )

DTC	Description	Status
P1260	Security input	

### TCM (Transmission Control Module (TCM)) ( 1 DTC )

DTC	Description	Status
P0706	Transmission range sensor circuit range/performance	

**IPK (Instrument Pack) ( 2 DTCs )**

DTC	Description	Status
U1260	SCP (+) circuit fault	
U1261	SCP (-) circuit fault	

**CCM (Climate Control Module) ( 3 DTCs )**

DTC	Description	Status
B1861-00	Climate control pressure switch circuit short to ground	
B1857-00	Climate control on/off switch circuit fault	
B1948-00	Climate control water temperature sensor circuit fault.	

**Technician Notes**

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.



Shop Name: --  
 Tel: --  
 Email: --  
 Address: --

Report ID: MAXIA20260408125333  
 Test Time: 2026-04-08 12:53:33  
 Technician: --

# 1998 Jaguar Vehicle Diagnostic Report

## Vehicle Information

1998/Jaguar/X300/BASE  
 VIN: SAJKX6248WC831715

Odometer Reading: 71697miles  
 License Plate: JAGUAR3

## Customer Information

Name: --

Tel: --

## Device information

Scanner: MaxiCOM MK808Z  
 Version: V1.70

Serial Number: DK1GP9C04107  
 Repair Order Number:  
 DK1GP9C0410720260406194241390

## System Scanned ( 14 )

System	Status/DTC
ECM	1
TCM (Transmission Control Module (TCM))	0
ABS	0
IPK (Instrument Pack)	2
CCM (Climate Control Module)	0
DDM (Driver Door Module)	0
PDM (Passenger Door Module)	0
DSM (Driver Seat Module)	0
PSM (Passenger Seat Module)	0
DRDM (Driver's (Side) Rear Door Module)	0
PRDM (Passenger's (Side) Rear Door Module)	0
SLM (Security Locking Module)	0
BPM (Body Processor Module)	0
ACM (Restraints Control Module (RCM))	0

## DTC ( 3 )

### ECM ( 1 DTC )

DTC	Description	Status
P1111	Since last memory clear, system check complete.	

### IPK (Instrument Pack) ( 2 DTCs )

DTC	Description	Status
U1260	SCP (+) circuit fault	

U1261 SCP (-) circuit fault

**Technician Notes**

Customer name: \_\_\_\_\_

Technician: \_\_\_\_\_

Date: \_\_\_\_\_

Note: Please save a copy of this report for your records.



Shop Name: --  
 Tel: --  
 Email: --  
 Address: --

Report ID: MAXIA20260408125805  
 Test Time: 2026-04-08 12:58:05  
 Technician: --

# 1998 Jaguar Vehicle Diagnostic Report

## Vehicle Information

1998/Jaguar/X300/BASE  
 VIN: SAJKX6248WC831715

Odometer Reading: 71697miles

License Plate: JAGUAR4

## Customer Information

Name: --

Tel: --

## Device information















Scanner: MaxiCOM MK808Z

Version: V1.70

Serial Number: DK1GP9C04107

Repair Order Number:  
 DK1GP9C0410720260406194241390

## System Scanned ( 14 )

System	Status/DTC
ECM	 1
TCM (Transmission Control Module (TCM))	 0
ABS	 0
IPK (Instrument Pack)	 0
CCM (Climate Control Module)	 0
DDM (Driver Door Module)	 0
PDM (Passenger Door Module)	 0
DSM (Driver Seat Module)	 0
PSM (Passenger Seat Module)	 0
DRDM (Driver's (Side) Rear Door Module)	 0
PRDM (Passenger's (Side) Rear Door Module)	 0
SLM (Security Locking Module)	 0
BPM (Body Processor Module)	 0
ACM (Restraints Control Module (RCM))	 0

## DTC ( 1 )

### ECM ( 1 DTC )

DTC	Description	Status
P1260	Security input	

## Technician Notes



Shop Name: --  
 Tel: --  
 Email: --  
 Address: --

Report ID: MAXIA20260411135339  
 Test Time: 2026-04-11 13:53:39  
 Technician: --

# 1998 Jaguar Vehicle Diagnostic Report

## Vehicle Information

1998/Jaguar/X300/BASE  
 VIN: SAJKX6248WC831715

Odometer Reading: 72295miles  
 License Plate: JAGUAR

## Customer Information

Name: --














Tel: --

## Device information

Scanner: MaxiCOM MK808Z  
 Version: V1.70

Serial Number: DK1GP9C04107  
 Repair Order Number:  
 DK1GP9C0410720260408140208730

## System Scanned ( 13 )

System	Status/DTC
ECM	 1
TCM (Transmission Control Module (TCM))	 0
ABS	 0
IPK (Instrument Pack)	 2
CCM (Climate Control Module)	 0
DDM (Driver Door Module)	 0
PDM (Passenger Door Module)	 0
DSM (Driver Seat Module)	 0
PSM (Passenger Seat Module)	 0
DRDM (Driver's (Side) Rear Door Module)	 0
PRDM (Passenger's (Side) Rear Door Module)	 0
SLM (Security Locking Module)	 0
ACM (Restraints Control Module (RCM))	 0

## DTC ( 3 )

### ECM ( 1 DTC )

DTC	Description	Status
P1111	Since last memory clear, system check complete.	

### IPK (Instrument Pack) ( 2 DTCs )

DTC	Description	Status
U1260	SCP (+) circuit fault	
U1261	SCP (-) circuit fault	

# Vehicle Diagnostic Report

Date&Time: 04/20/2026 07:31

Path:

VIN:

Jaguar  
V1.70



Auto scan

14.07V

## System List

100%

10	DRDM (Driver's (Side) Rear Door Module)	Pass No Fault
11	PRDM (Passenger's (Side) Rear Door Module)	Pass No Fault
12	SLM (Security Locking Module)	Pass No Fault
13	BPM (Body Processor Module)	No response
14	ACM (Restraints Control Module (RCM))	Pass No Fault
15	ADS (Adaptive Damping System)	Scanning...

VIN: SAJKX6248WC831715  
Info: Jaguar/X300  
SN: DK1GP9C04107

Report

Quick  
Erase

OK

Pause

ESC