



All

DATE 8/98

1-97

SERVICE

ADMINISTRATION BULLETIN

Portable Diagnostic Unit Software Issue –
JTP626/2 – Replaces PDU 5005

MODEL
1990-94 MY Sedan
1990-96 MY XJS
VIN
594576-708757
165791-226645

ISSUE:

JTP626/2 for the 1990-94 MY Sedan Range and 1990-96 MY XJS has been released and contains upgrades to all the software that was previously available on PDU 5005 and items from PDU 1055 such as datalogger, vehicle set-up, and vibration analyzer.

ACTION:

Ensure that this software is installed immediately. Retain PDU 5005 in a secure place as a backup CD-ROMs in the event JTP626/2 is damaged.