

TECHNICAL BULLETIN



Bottom Radiator Hose - Foul on Anti-Roll Bar -
No Action Required

26-13

MODEL 94 MY XJ12

DATE 3/94

ISSUE:

The bottom radiator hose may come in contact with the anti-roll bar when the engine is at normal running temperature.

This contact is minor and will not result in any significant wear to the hose material.

Shortening the hose to provide clearance from the anti-roll bar may result in the hose fouling the air pump drive belt. This action should NOT be taken.

ACTION:

None

.....
Index # 037560
.....