
## 1994 MY XJS



Remove the gearshift lever selector bezel. Gently press down on the interlock release with a screwdriver through the access hole. Move the shift lever out of PARK.