



Spacer in question.

When bolt is torqued up it does Nothing!

Shock cannot pivot with suspension movement, rubber in bush is clamped between "ears" of rear subframe and is in torsion.