



SSM46917 - Gasoline Fuel Additive For Clogged Fuel Injectors

Reference	SSM46917
Models	Discovery 3 Discovery 4 New Range Rover Range Rover Sport
Title	4.2/4.4/5.0 Gasoline Fuel Additive For Clogged Fuel Injectors
Category	Engine
Last modified	31-Jan-2011 00:00:00
Symptom	499000 Basic Engine
Content	<p><u>Issue:</u></p> <p>Fuel injectors clogged leading to potential problems such as poor running, poor fuel economy, excessive exhaust emissions, hard starting, rough idle, misfires and engine detonation.</p> <p><u>Cause:</u></p> <p>Poor fuel quality or fuel contaminants restricting the fuel injector flow rate.</p> <p><u>Action:</u></p> <p>Land Rover engineering now approve the use of BG 44K Power Enhancer Cleaner (which is sold in an 11oz/325ml can or bottle) on 4.2/4.4 AJV8 and 5.0 AJ133 Gasoline engine derivatives.</p> <p>The above mentioned additive should be used in the first instance in an attempt to cure a suspected 'clogged' injector (misfire DTC maybe stored) rather than unnecessary replacement.</p> <p>NOTE: Land Rover recommend only using the above product a maximum of twice between each 15K service.</p> <p>Further information on the additive can be found on the BG Products website http://www.bgprod.com/products/fuelair.html</p>