

Anthony's
JAG

VEHICLE DIAGNOSTIC REPORT

Amazing Automotive & Trans

90 Route 46, Rockaway, NJ, 07866

Tel: 973-586-2191 Fax: 973-586-2519 Email: amazingautomotive11c@gmail.com Web: amazingautomotiveandtransmissions.com

Date & Time: 08/31/2015 13:55

Path: Diagnosis\Auto Scan\

VIN: SAJJA42C0YNA09347

Auto Scan

1	ABS - ABS control module	Fault 1
2	ECM - Engine control module	Fault 3
3	IPK - Instrument pack	Fault 1
4	TCM - Transmission control module	Pass No Fault
5	DSM - Driver's seat module	Pass No Fault
6	PSM - Passenger's seat module	Pass No Fault
7	SLM - Security locking module.	Pass No Fault
8	PDM - Passenger's door module	Pass No Fault
9	DDM - Driver's door module	Pass No Fault
10	BPM - Body processor module	Pass No Fault

VEHICLE DIAGNOSTIC REPORT

Amazing Automotive & Trans

90 Route 46, Rockaway, NJ, 07866

Tel: 973-586-2191 Fax: 973-586-2519 Email: amazingautomotive@gmail.com Web: amazingautomotiveandtransmissions.com

Date&Time: 08/31/2015 13:56

Path: Diagnosis\Auto Scan\Read Codes\

VIN: SAJJA42C0YNA09347

Read Code

Code	Status	Description
U2500		CAN bus error.

VEHICLE DIAGNOSTIC REPORT

Amazing Automotive & Trans

90 Route 46, Rockaway, NJ, 07866

Tel: 973-586-2191 Fax: 973-586-2519 Email: amazingautomotive@gmail.com Web: amazingautomotiveandtransmissions.com

Date & Time: 08/31/2015 13:57

Path: Diagnosis\Auto Scan\Normally aspirated\Read Codes\

VIN: SAJJA42C0YNA09347

Read Code

Code	Status	Description
P0171		System too lean Bank 1
P0174		System too lean (bank 2).
P1000		System check not completed since last memory clear

VEHICLE DIAGNOSTIC REPORT

Amazing Automotive & Trans

90 Route 46, Rockaway, NJ, 07866

Tel: 973-586-2191 Fax: 973-586-2519 Email: amazingautomotive@gmail.com Web: amazingautomotiveandtransmissions.com

Date & Time: 08/31/2015 13:57

Path: Diagnosis\Auto Scan\Normally aspirated\Read Codes\

VIN: SAJJA42C0YNA09347

Read Code

Code	Status	Description
U1260		SCP (J1850) (+) circuit failure.
