

**2009 Emissions-Related Recall Campaigns through December 2009**

Mfr.	Mfr. Recall Number	EPA#	Type	Owner Notification	MY	Vehicle or Engine Class	Engine Family	Problem Description	Affected Vehicles	Total Number of Vehicles Recalled
Jaguar	J004	3536	V	12/1/2008 (Rec'd VERR 10/30/2009)	2004	S-Type, X-Type, XK8, XKR, S-Type, XJ8, XJR	4JCV03.0DNE 4JCV03.0DNG 4JCV04.2DN9 4JCV04.2DNF 4JCV04.2DSA 4JCV04.2DSB	The On-Board Diagnostics (OBD) system may not correctly detect tailpipe or evaporative emissions failures and provide the applicable warnings to the driver. <b>Remedy:</b> Dealers will reconfigure Engine Control Module (ECM) and, where appropriate, the Transmission Control Module (TCM).	5,276	98,581
					2005	S-Type, X-Type, XK8, XJ8, VDP, XKFi, Super V8, XJR	5JCV03.0DNE 5JCV03.0DNE 5JCV03.0DNE 5JCV04.2DN9 5JCV04.2DNF 5JCV04.2DSA 5JCV04.2DSB		24,800 991 17,637 564 2,664 8,862 6,064 5,208 1,766	
					2006	X-Type, XK8, XKFi	6JCV03.0DNH 6JCV03.0DNH 6JCV04.2DSA		10,520 724 2,346 5,981	
					2007	X-Type	7JCV03.0DNH		1,462 710 3,017	