

All

DATE 12/03

1-167

SERVICE

ADMINISTRATION BULLETIN

Mandatory Special Tool – 303-1077

MODEL AJ V8 from engine no. 0108100000

Issue:

Special tool 303-1077 has been shipped to Jaguar retailers.

Global Tool No. Description




ILLUSTRATION 1

Special tool 303-1077 is used during the removal and installation of the V8 camshaft sprocket securing bolts from engine number 0108100000 onward.

Action:

Retain the 303-1077 service tool in a suitable location within the top draw of the JAG.059-USA & JAG.074 tool cabinet. A permanent tool location will be indicated in a future release of the applicable tool finder sheets.

Additional supply of the items listed above can be ordered by calling the SPX customer support line at 1-800-533-5338.

Ensure that these service items have been supplied and free of damage within your shipment. To report any damage or discrepancy pertaining to your shipment, please contact the SPX customer support line at 1-800-533-5338. Any claim against this shipment must be made within 30 days of receipt at your facility.

