

DTC: C1288

CM: DSCCM

System: Dynamic stability control

Fault Description: Brake pressure sensor circuit fault

CM Pin: JB185 - 25 26 42

Possible causes : Brake pressure sensor circuit: open circuit, short circuit, high resistance. Brake pressure sensor failure