


5.0 Cylinder Block Oil Gallery Plug Leak



Land Rover Part Number LR008871

Please ONLY fit a RED plug as shown below:

