

2011.75 XJ RANGE (X351), 501-09

REAR VIEW MIRRORS

INTERIOR REAR VIEW MIRROR

[G1267494]

REMOVAL AND INSTALLATION

REMOVAL


NOTE:

Some variation in the illustrations may occur, but the essential information is always correct.


1.

CAUTIONS:


- Take extra care not to damage the clips.
- Protect the surrounding trim to avoid damage.



E125685




2.



E99900

3.




E99901

INSTALLATION

1.



2.





3.

CAUTION:

Take extra care not to damage the clips.

NOTE:

For vehicles with Auto high beam assist (AHBA) the Interior mirror cover caps are designed for one fit only, therefore should be replaced.



E125792