
# JAGUAR X300 QUICK NOTES


JOE BARRY 816-807-3946 10622 N.Charlotte KCMO 64155




No.	Description	Price	Quantity
1	+ Pinion locknut		
2	+ Collapsible spacer		
3	+ Pinion bearing		
4	+ Taper roller bearing		
5	+ Xylan coated washer		
6	+ Pinion oil seal		
7	+ Companion flange		
8	+ Pinion head shim kit		
9	+ Drive shaft		
10	+ .Stud		
	OFFIC	AL	
11		AR #'s	

No.	Description	Price	Quantity
	JEVH 2168	£45.38	1 1 ADD
12	+ .Retaining plate		
13	+ .Torx head bolt		
ı	+ .TOIX flead boil		
14	+ .O-ring		
	<u> 11,4625</u>	£5.51	5 ADD
15	+ .Ball bearing		
	37.15	us	1 1 ADD
16	+ .Shaft bearing retaining collar		
	ULM615	£41.37	1 1 ADD
17	+ DrIve shaft shim kit		
18	+ Nut		
19	+ Roller bearing		
ı			
20	+ Differential bearing shim kit		
21	+ Differential		

No.	Description	Price	Quantity
22	+ Crownwheel and pinion		
ı			
23	+ Drive gear bolt		











**JLM621** 



JLM11527



**JLM615** 

# What's the difference between Torx® and Torx Plus® bits?

Torx Plus® bits and fasteners feature a greater engagement area for higher torque transfer and reduced camout when driving Torx Plus® fasteners. They can provide up to 100% more drive cycles.


Torx Plus® bits are not compatible with standard Torx® fasteners.

Regular Torx®


Torx Plus® is a trademark of the Camcar Division of Textron.
Torx Plus® Tamper Resistent Bits are available on a limited basis. Please contact your Area Distributor or Representative for more details.



### HARRY EPSTIENS TOOLS 301 8th ST downtown







### speakerworks.com

5 1/4 inch Speaker Repair Kit Angled or Flat Attach with 1 Foam Surround - SWK525


Price: \$8.95 Sale Price: \$5.95 You save \$3.00!

Nitrile Rubber Adhesive (Best For Plastic Speaker Cones) [Add \$0.99]









AUX / CD / MP3 input Mod AJ9500R cassette board pic

# JOE BARRY 816 807 3946

shopcenturyautoair.comshopcenturyautoair.com	NOT equivalent to fault codes.		skip actuator check)	and HRW			and RECIRC - Switch		T edure via the Control Panel	Climate (
	t codes.	Exit error check mode	Initiate actuator check (Actuator	ored fau	Scroll through stored faults (max	Any stored fault NUMERIC code no stored codes)	Display element check	Result	and	Control Systems

shopcenturyautoair.com denso 10PA17C for Jaguar X300

YOUTUBE Video; Denso 10PA Series Compressor Reseal Part 1 and 2

Denso 10PA Series Master Reseal Kit KT-10PA-SYS SKU:



DENXO 10PA17C Clutch Bearing NSK 30BD5222DUM6 30mm ID x 52mm OD x 22mm Thick.jp





DENSO+10PA15C+10PA17C+10PA20C+AC+clutch+coil

eurtonelectric.com Tel: (800) 423-4789 .15" x .15" x .35" BRUSH 33A

Price: \$4.50 x 2 per motor







## **Selecting The Right Chemistry**



### **Zerex Original Green**

- Traditional green chemistry found in most early model year vehicles
- · Low silicate formula is ideal for heavy duty applications
- Protects all cooling system metals while providing excellent high-temperature aluminum protection
- Meets and/or exceeds the following industry and engine specifications: GM1825M, GM 1899M, Ford ESE-M97B44-A, Chrysler MS 7170, ASTM D3306 & D4985, SAE J1034, J814C & J1941, TMC of ATA RP-302B, Federal Specifications A-A-870A, Detroit Diesel 7SE298, Cummins 90T8-4
- · Product Color: Green

6/1 GALLON ZX001 Ready-To-Use



### Zerex G-05

- 5 Year / 150,000 Mile Guarantee
- . HOAT chemistry APPROVED for use in Mercedes Benz and newer Ford & Chrysler vehicles (see owner's manual for specific model years)
- Phosphate Free for use in European vehicles such as Volvo, BMW & MiniCooper
- Fully formulated to help prevent liner pitting in heavy duty diesel engines
- Meets and/or exceeds the following industry and engine specifications: Chrysler MS9769. Ford WSS-M97851-A1, ASTM D3306, GM 1825M, GM 1899M, MTU MTL 5048, John Deere JDM H24, and MAN List 3.3.7

55 GA DRUM

Product Color: Yellow

Concentrate

Ready To-Use



### Zerex DEX-COOL

- 5 Year / 150,000 Mile Guarantee
- OAT DEX-COOL APPROVED for use in GM vehicles produced since 1996 and SAAB vehicles since 2001
- Meets and/or exceeds the following industry and engine specifications: GM6277M, ASTM D3306, SAE J1034, J814 and J1941, TMC of ATA RP-302B, and Federal Specification A-A-870A
- Product Color: Orange
   6/1 GALLON

Concentrate Ready-To-Use




- 5 year /150,000 Mile Guarantee
- · Silicate free, phosphated HOAT Chemistry specified by Asian vehicles
- Recommended for Toyota/Lexus, Honda/Acura, Nissan/Infiniti and other Asian vehicles
- Meets or exceeds the following industry and engine specifications: Hyundai/Kia MS 591-08, Mitsubishi ES-64217, JIS K 2234-1994, ASTM 03306, ASTM D4985, Ford WSS-M97B55-A
- · Product Color: Pink

Ready-To-Use

55 GA DRUM

TO PLACE AN ORDER OR FOR MORE INFORMATION CALL 800-TEAM-VAL


DEX-COOL is a registered trademark of General Motors Corporation, used under license









**DIRTY** 






3 and 9 o'clock plastic tabs go aft or above chrome tabs







SECURITY MODULE CONNECTOR ( also LS3 – x ,RS3




A/C EXPANSION VALVE INSIDE CABIN BURIED valve is forward of evaporator plate



Just cut plain mirror material . See You Tube video

### ENGINE TROUBLE **PI (Indy)1** - x

13-way FONOSEAL III



### Rear of the RH headlamp PII - 13-Way ECONOSEAL III LC / WHITE and


PI61 - 13 way ECONOSEAL III LC / BLACK.


```
PII-1 should be WY / WY
PI1-2 should be GB / GB
PI1-3 should be NY / NY
PI1-4 should be WK / WK
PI1-5 should be WO / WO
PI1-6 should be NO / NO
PI1-7 should be RS / RS
PI1-8 should be OS / OS
PI1-9
PI1-10
PI1-11 should be KB / KB
PI1-12 should be RO / RO
PI1-13 should be UW / UW
```

### PI61-1

PI61-2 should be WU / WU
PI61-3 should be R / R
PI61-4 should be WU / WU
PI61-5
PI61-6 should be S / S
PI61-7 should be KN / KN
PI61-8 should be KR / KR
PI61-9 should be UR / UR
PI61-10 should be NLG / NLG
PI61-11 should be BW / BW
PI61-12 should be WG / WG
PI61-13 should be NO / NO

The colours are N = Brown, B = Black, W = White, K = Pink, G = Green, R = Red, Y = Yellow, O = Orange, S = Slate, L = Light, U = Blue, P = Purple.





# 2X SWITCH FOR REPAIR EBAY



CHEEP
LEATHER
RESORE
ONLY
FOUND AT
SALLY
BEAUTY
SUPPLY

BARRY AND NORTH OAK

use medium toothbrush / let set









# CRACK-















D				Α	
				7	1
				8	2
					3
E				В	
					4
					5
					6
F				С	




### LNA6706AA

### CIGAR LIGHTER







Normal Operation rotate to passenger side

Middle bar slides to driver side


Hidden bar rotates to driver side to open




**BATTERY TRAY and Springs** 







A/C Temp Sensor



V\$4721





# BILGTEIN

