



Sedan Range

DATE 3/97

1-80

SERVICE

ADMINISTRATION BULLETIN

Portable Diagnostic Unit Software Issue –
PDU 5005

MODEL 1990-94 MY
Sedan Range
VIN
594576-708757

ISSUE:

PDU 5005 has been released and replaces PDU 5000. This CD-ROM contains all the 1990-94 MY Sedan Range software that was available on the following JDS disks:

- DBC 4040
- DBC 4050
- DBC 4060
- DBC 4070

ACTION:

Ensure that this software is installed immediately. Retain PDU 5000 in a secure place as a backup CD-ROM in the event 5005 is damaged.