



Sedan & XJS

DATE 10/97

1-89

SERVICE

## ADMINISTRATION BULLETIN

Portable Diagnostic Unit Software Issue –  
PDU 1055

MODEL 1995 MY-ON  
Sedan Range & XJS  
VIN

**ISSUE:**

PDU 1055 has been released and contains upgrades to all the software that was previously available on 1045. In addition, it includes 1998 XJ8 new model diagnostics. The Teves ABS diagnostic connector is included in this mailing as part of the 1998 diagnostics package.

**ACTION:**

Ensure that this software is installed immediately. Retain PDU 1045 in a secure place as a backup CD-ROM in the event 1055 is damaged.