



Handwritten notes: 1001, 11/21/14, P.K.

An independently owned and operated AAMCO Center

INTERNAL USE ONLY

SC	WC	SERVICE DESCRIPTION	PRICE
----	----	---------------------	-------

DESCRIPTION OF PROBLEM-- CUSTOMER STATES THAT THE TRANSMISSION GOES INTO FAIL SAFE, HAS HAD A SERVICE DONE

AAMCO MULTI-POINT INSPECTION

AUTHORIZATION: BY: GLENN DATE: 5/21/2014 TIME: 2:48:29 PM FROM: CUSTOMER PHONE: _____

39.95

DESCRIPTION OF PROBLEM-- CUSTOMER STATES THAT THE TRANSMISSION GOES INTO FAIL SAFE, HAS HAD A SERVICE DONE

TRANSMISSION SERVICE

AAMCO MINOR REPAIR WITH A NINETY (90) DAY WARRANTY ON PARTS REPLACED AND LABOR. PROVISIONAL REPAIR

--
LABOR TO INSTALL

--
NEW - TRANSMISSION FLUID FILLED TO MANUFACTURER'S SPECIFICATION

18.75

1 NEW - CASE CONNECTOR

19.95

--
LABOR

LABOR - VEHICLE TOW CHARGE

142.50

60.00

1 --
CREDIT - MPI

-39.95

AUTHORIZED TRANSMISSIONS SERVICE AMOUNT \$243.61

AUTHORIZATION: BY: GLENN DATE: 5/22/2014 TIME: 9:41:33 AM FROM: MS PHONE: _____

**SHOP SUPPLIES/ DISPOSAL 2.41

PARTS SHOWN AS EXCHANGE ARE NOT RETURNABLE

TRANSMISSION				Total Car Care			
PARTS: 38.70	LABOR: 202.50	SUBTOTAL: 241.20		PARTS: 0.00	LABOR: 0.00	SUBTOTAL: 0.00	

TOTAL LABOR	202.50
TOTAL PARTS	38.70

ADDITIONAL INFORMATION: SYSTEM LEAN CODES, ENGINE HAS A CONSTANT MIS, THIS COULD MEAN RAW FUEL COULD DUMP INTO EXHAUST AND THIS WOULD CAUSE THE CAT CONVERTERS TO FAIL, CASE CONNECTOR WAS LEAKING, HAD FLUID IN IT. HAS A WEAK BATTERY, WE HAD TO JUMP TO START, HAS VACUUM LEAK AT UPPER INTAKE.

SUBTOTAL	243.61
TAX	18.27
TOTAL	261.88

CERTIFICATION

This certifies that the automotive components described above have been properly repaired and restored to sound working condition.

COMPLETION CERTIFICATE

I acknowledge receipt of the vehicle and a copy of this Repair Order.

Authorized Signature

Authorized Signature

Delivery Date