



# DYNOLINK

## Mainline DynoLog Chassis Dyno Report

AWD Dyno Service  
16 Civil Road  
Garbutt Qld 4814  
Ph: 07 4755 0000  
Fax: 07 4775 3513

• Test ID: **TUNE CHECK**

Customer:

Heads:

Test Date: **16-Oct-2013 15:45**

Camshaft:

Test #: **18975** Operator: **ADRIAN**

Exhaust:

Rego No: **106SIM** VIN: **SAJJPALF3CR841971**

Manifolds:

Vehicle: **98 XJR V8**

Induction: **SUPERCHARGED**

Fuel: **ULP**

Capacity: **0.0 ci**


Air Density: **0.0%**

Odometer: **140,818**

Gear: **4**

Correction: **5.45 SAE J607** (30.2°C, 1013mBar, 61%) Cylinders: **8**

• Compare Run: **TUNE CHECK / 18974, 16-Oct-2013, 15:40**



Max: ■ Torque= **752N.M @ 70KPH**    ● Power= **257KW @ 196KPH**    ▲ Motive Force= **5573.1N @ 70KPH**  
 Max: ■ Torque= **744N.M @ 142KPH**    ● Power= **256KW @ 184KPH**    ▲ Motive Force= **5509.2N @ 142KPH**

