

Instrument Panel and Console - Glove Compartment



Removal and Installation


Removal

• NOTE: Removal steps in this procedure may contain installation details.

1. Refer to: [Passenger Side Register](#) (412-01 Climate Control, Removal and Installation).

2.





3.  CAUTION: Fixings must be started by hand to avoid damaging threads.

- Upper 3 bolts.

- Torque: 2.5 Nm
- Lower 3 bolts.



Torque: 9 Nm

4.



E96847

5. **5. NOTE:** Do not disassemble further if the component is removed for access only.



E96848

Climate Control - In-Vehicle Temperature Sensor

Removal and Installation

Removal

- NOTE: Removal steps in this procedure may contain installation details.

1. Refer to: [Glove Compartment](#) (501-12 Instrument Panel and Console, Removal and Installation).

2.



Installation

1. To install, reverse the removal procedure.