
# 1998 XJ RANGE - Interior Trim and Ornamentation - 501-05

## Passenger Assist Handle 76.58.30

#### Removal



### E36225

- 1. Using a piece of wood or similarly soft material, press inner end of each screw cover to release outer clip.
- 2. Remove screw covers, slacken and remove securing screws and remove grab handle from cantrail.

### Installation

- 1. Position grab handle and coat hanger hook at cantrail
- 2. Ensuring that cantrail trim pads are correctly aligned, fit and tighten the grab handle securing screws.
- 3. Slide each screw cover inner end foremost, onto end of grab handle and press outer end to engage clip.

1

2011-06-16