





VEHICLE AND RE	ETAILERANFORMATION	,	
Inspection Date 7/2/3030		Complete VINSATWAYHAX DMB49613	
Repair Order Number	116574	Acquisition Date In BBSS	•
Retailer Code	5768	Original In-Service Date	
Retailer Name	good of Tampa	Current Mileage 40, 549	
Vehicle Model		Date/Mileage Last Service Performed	
Model Year 201	3	Date/Mileage Next Service Due	
	SHOULD TAKE 1.5 - 2 HOURS IE DETAILS PLEASE REFER TO LIVING JAGUAR GUIDELINES	Next scheduled service should be performed if within 3,000 miles/90 days of next next next next next next next next	
MEETS JLR PREPARATION STANDARDS  APPRO	OVED CERTIFIED PRE-OWNER	D 165-POINT INSPECTION CHECKL	IST
1 Was 2 Does 2 Does 3 Has to indep 4 Is the approx 6 Does 7 Does inform 8 Have STOP If "NG Servi	E ELIGIBILITY  the vehicle built for sale in the US?  vehicle meet age, model year and mileage of the vehicle passed an independent Vehicle Hondent Mileage Check?  vehicle free from any warranty restrictions?  vehicle free from current or evidence of no oved aftermarket modifications?  the vehicle have a complete service history the windshield VIN plate number match the mation on A/B pillar/ driver's door area?  all outstanding Recalls and Service Campaign  D" to any of the above, STOP and notify the ce Manager and Pre-Owned Manager.  IINARY CHECKS  er's Manual complete and present?	distory and  Property and  Property and  Property and a second and a s	
10 All ke  ves No N/A INTERIO  11 Gene  12 Vene  13 Glove  14 Ashtr  15 (IF Ec  16 Sun V  17 Restr  18 Seat  19 Child  20 Seat  21 Steer  22 Door  23 Seats  24 Carpo  25 Head  26 Head  27 (IF Ec	OR - GENERAL  ral interior condition er, wood, leather and headliner e box, console box and trim ray and stowage compartment door QUIPPED) Roof opening panel and roof bline visor and vanity mirror raint/airbag system Occupant Sensing system safety door latches belts ring column and steering lock handles (interior)	eys d	





Yes NO N/A TESTS - STATIONARY	COMMENTS			
Mileage Before Mileage A	After			
133 Hot/cold start	11161			
NO. 100				
134 Engine noises				
2 135 Engine idling				
136 Fuel pump/lines/hoses				
137 Starter/alternator				
138 Instrument pack gauges				
139 Fluid leaks				
Yes NO N/A TESTS - ROAD				
140 (IF EQUIPPED) Electronic Air Suspension				
141 Trip computer				
2 142 Engine performance				
143 Vibration	•			
144 Wind noise				
145 Stability and pull				
146 General handling				
147 Steering wheel alignment				
147 Steering wheer alignment 148 Brake pedal				
<i>7</i>				
149 ABS braking system				
150 Emergency brake				
151 Squeaks and rattles	C) Custom			
152 (IF EQUIPPED) Dynamic Stability Control (DSC	C) System			
and Electronic Traction Control (ETC) System	Mada			
153 JaguarDrive Control™ (IF EQUIPPED) Winter N	-tode			
154 Cruise Control				
155 (IF EQUIPPED) Adaptive Cruise Control				
156 (IF EQUIPPED) Forward Alert				
157 (IF EQUIPPED) Head Up Display				
158 (IF EQUIPPED) Stop/start system				
7 _ 159 (IF EQUIPPED) Automatic transmission				
160 (IF EQUIPPED) Manual transmission and clutcl	h			
[ 161 (IF EQUIPPED) Blind Spot Monitor				
162 (IF EQUIPPED) Navigation system				
🗒 🦵 / 163 (IF EQUIPPED) Deployable rear spoiler				
[] 164 (IF EQUIPPED) Convertible folding top				
,				
Yes NO N/A TESTS - EMISSIONS				
165 Emissions tests				
	10,000 mm			
TECHNICIAN NOTES:				
3.100 ಟ್ರೆ ಬೆಳಗಳ ವರ್ಷದ ಗ್ರಾತ್ ಕರ್ಮನ್ ಬಡುಗಳು				
SIGNATURES				
Technician, Service Manager and Pre-Owned Manager signatures certify (i) the vehicle has been inspected against the				
Jaguar Approved Certified Pre-Owned program standards prior to being advertised and marketed as a Jaguar Approved				
Certified Pre-Owned vehicle (ii) prior to the sale of the vehicle, the retailer will provide the customer with a completed				
inspection report indicating all the components inspected, as required.				
dobe - total - ell				
Inspection Technician Name	Pre-Owned Manager			
RA AGOS LOS				
Signature	Signature			
7/7/2020				
Date	Date			
l .				
Service Manager Name				
	INSPECTION SHOULD TAKE 1.5 - 2 HOURS.			

Date