

Pre-purchase Inspection Report

16

 / 100

Car: Jaguar XKR 4.0L Petrol 1998

VRM: G13PJD

Mileage: 121,122 miles

Mechanic: Ben Maundrill
of 1ST GEAR AUTOS LTD

Report created: 6th June 2024, 10:21AM

About Ben: Hi we are 1st Gear Autos Ltd, we have over 20 years combined experience working on a variety of light vehicles and hgvs. No job is ever too big or too small. We are fully mobile or you can come to our workplace in Doncaster.

Disclaimer: *Please note, this is an inspection only and represents your mechanic's professional evaluation of the vehicle at the time of inspection. There is no offer of warranty with this service. This report is for information only and is not to be considered a recommendation for or against the purchase of the inspected vehicle.*

Interior compartment

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Door locking			●		In working condition
Boot/tailgate lock			●		In working condition
Door seals			●		In working condition
Door hinges			●		In working condition
Door trim panels		●			Some wear due too age
Dash panel condition			●		In working condition
Interior sills			●		In working condition
Illuminating lights			●		In working condition
Seat upholstery		●			Some wear due too age
Seat mechanism (front seats)			●		In working condition
Steering wheel adjustment			●		In working condition

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Rear view mirror condition			●		In working condition
Cigarette lighter			●		In working condition
Headlining			●		In working condition
Visors			●		In working condition
Carpets			●		In working condition
Sunroof condition	—	—	—	—	Not fitted
Rear parcel shelf			●		In working condition
Rear luggage area condition			●		In working condition
Tool kit			●		In working condition
Charging ports	—	—	—	—	Not fitted
Seat belts			●		In working condition

Electrical/controls

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Headlights			●		In working condition
Side light/running lights			●		In working condition
Indicators/hazard lights			●		In working condition
Rear lights/number plate lights			●		In working condition
Stop lights			●		In working condition
Reverse/fog lights			●		In working condition
Auxiliary lights			●		In working condition
Panel lights			●		In working condition
Switches/controls (Condition & Operation)			●		In working condition
Instrument/controls function			●		In working condition
Horn	●				The horn does not work
Windows/sunroof operation		●			Windows work but drivers window switch broken
Front windscreen wipers			●		In working condition

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Front windscreen washers			●		In working condition
Rear wiper	—	—	—	—	Not fitted
Rear washer	—	—	—	—	Not fitted
Headlamp washer	—	—	—	—	Not fitted
Headlamp wiper	—	—	—	—	Not fitted
Electric/manual mirrors operation			●		In working condition
CD / Radio operation			●		In working condition
Interior lights			●		In working condition
Battery voltage			●		In working condition
Climate control/heater fan controls		●			Work but screen damaged
Screens (info/entertainment)	—	—	—	—	Not fitted
Key Fobs	●				Key fob Does not work
Manual locking key blade & operation			●		In working condition
Steering wheel controls			●		In working condition

Road test

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Driving test (up to 5 miles)			●		In working condition
Starting system/ignition lock			●		In working condition
Warning lights	●				Suspension malfunction on dash
Cold starting			●		In working condition
Fast idle (cold)			●		In working condition
Noise level (cold)			●		In working condition
Excess fumes/smoke			●		In working condition
Engine - noise level			●		In working condition
Engine - general performance			●		In working condition
Overheating evidence			●		In working condition

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Turbo/super charger operation & noise			●		In working condition
Battery charging system			●		In working condition
Hand/parking brake operation	●				Hand brake lever does not work
Footbrake operation			●		In working condition
Gearbox operation/noise level			●		In working condition
Clutch operation			●		In working condition
Accelerator Pedal Operation			●		In working condition
Instrument/controls function			●		In working condition
General steering/handling			●		In working condition
Road holding/stability			●		In working condition
Suspension noise			●		In working condition
Cruise control			●		In working condition
Steering wheel alignment			●		In working condition
Steering effort			●		In working condition
Four wheel drive operation	—	—	—	—	Not fitted
Suspension ride height level operation	●				Suspension fault on dash
Air con operation			●		In working condition
Final drive operation/noise level			●		In working condition
Hot restarting			●		In working condition
Cooling fan operation			●		In working condition
Stop-start system	—	—	—	—	Not fitted
Hill start system	—	—	—	—	Not fitted
Automatic transmission operation & shifts			●		In working condition

Engine compartment

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Bonnet catch			●		In working condition
Bonnet hinges			●		In working condition
General cleanliness of engine bay			●		In working condition
Coolant/antifreeze level			●		In working condition
Coolant leaks			●		In working condition
Radiator / expansion bottle cap			●		In working condition
Hoses/pipes			●		In working condition
Engine oil level			●		In working condition
Drive belts (visible damage)			●		In working condition
Water pump operation			●		In working condition
Power steering fluid level			●		In working condition
Clutch fluid level			●		In working condition
Brake fluid level			●		In working condition
Engine mountings			●		In working condition
Fuel Injection Leak Off Pipe Condition (if visible)			●		In working condition
External leaks			●		In working condition
Accelerator links			●		In working condition
Fuel pump/pipes			●		In working condition

Wheels & tyres

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Front right tyre			●		In working condition
Front left tyre			●		In working condition
Rear right tyre			●		In working condition
Rear left tyre			●		In working condition
Uneven tyre wear			●		In working condition
Spare wheel condition	●				No tyre on space saver rim

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Locking wheel nut key	—	—	—	—	Not fitted
Wheel rims			●		In working condition
Wheel trims	—	—	—	—	Not fitted
Alloy wheel condition (if applicable)			●		In working condition
Tyre inflation kit	—	—	—	—	Not fitted

Bodywork & exterior

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Glass			●		In working condition
Door locks/operation			●		In working condition
Fuel filler cover/petrol cap			●		In working condition
Body damage			●		In working condition
Windshield (condition)			●		In working condition
Past repairs evident			●		In working condition
Corrosion			●		In working condition
Paint work			●		In working condition
Mud flaps			●		In working condition
Bumper			●		In working condition
Number plate			●		In working condition
Panel condition			●		In working condition

Front suspension, brakes & steering

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Wheels hubs/bearings	●				O/s/f missing 2 wheel studs
Brake pads (visual check)	●				Brake pad material Broken off
Brake discs (visual check)		●			Discs are Slightly pitted
Brake pipes/hoses (where visible)			●		In working condition

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Road springs			●		In working condition
Shock absorbers (condition/leaks)			●		In working condition
Bump stops/gaiters			●		In working condition
Suspension arms/mountings			●		In working condition
Suspension arms/fixings			●		In working condition
Tie bars/anti roll bars			●		In working condition
Location rod/fixings			●		In working condition
Bushes			●		In working condition
Steering joints/ball joints			●		In working condition
Steering rack			●		In working condition
Power steering			●		In working condition

Rear suspension & brakes

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Wheels hubs/bearings			●		In working condition
Brake pads (visual check)			●		In working condition
Brake discs (visual check)		●			Discs slightly pitted
Brake pipes/hoses (if visible)			●		In working condition
Road springs			●		In working condition
Shock absorbers (condition/leaks)			●		In working condition
Bump stops/gaiters			●		In working condition
Suspension arms/mountings			●		In working condition
Suspension arms/fixings			●		In working condition
Tie bars/anti roll bars			●		In working condition
Bushes			●		In working condition

Brake hydraulics

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Master cylinder security (if accessible)			●		In working condition
Fluid leaks			●		In working condition
Servo/power system			●		In working condition
Flexible hoses			●		In working condition
Pipes/connections			●		In working condition

Clutch and transmission

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Fluid/oil leaks			●		In working condition
Hydraulic system			●		In working condition
Linkage wear (manual)			●		In working condition
Casings			●		In working condition
Mountings			●		In working condition
Drive shaft assemblies			●		In working condition
Sliding joints (if visible)			●		In working condition
Slave cylinder gaiter/boot (manual)			●		In working condition
Propshaft(s)			●		In working condition
Bearings			●		In working condition
Clutch pedal			●		In working condition
Clutch cable adjustments			●		In working condition
4WD transmission (if applicable)	—	—	—	—	Not fitted
Dual mass flywheel (noise/vibration)			●		In working condition

Underside condition

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Chassis members		●			Slightly rusting on rear
Sub frames/mountings		●			Rear subframe rusting
Corrosion - floor/chassis			●		In working condition
Corrosion protection	—	—	—	—	Not fitted
Engine underside leakage			●		In working condition

Fuel system

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Tank fixings			●		In working condition
Fuel lines			●		In working condition
Breather pipes			●		In working condition
Evidence of leaks			●		In working condition
Fuel tank (if accessible)			●		In working condition

Exhaust system

	Poor	Fair	Good	Excellent	Notes & Advice from Mechanic
Operation			●		In working condition
System condition			●		In working condition
Exhaust manifold (condition)			●		In working condition
Exhaust pipes (condition)			●		In working condition
Catalytic converter (condition)			●		In working condition
Heat shields condition			●		In working condition
DPF Condition (soot content with plug-in)			●		In working condition

Other notes

Additional points of note from the mechanic:

- Hand brake inop

Definitions

Excellent - Like new condition

Good - In working condition

Fair - May require some repairs

Poor - Requires some repairs

* Please note that it is not always possible for the mechanic to undertake all 185 checks. This may be due to the vehicle not being fitted with certain systems and features, or particular parts or areas of the car not being accessible or not being visible. The report will indicate where this is the case.

About ClickMechanic

ClickMechanic is a network of independent mobile mechanics and garages - who repair, service and inspect vehicles wherever needed, saving car owners time and money!

[VISIT US AT CLICKMECHANIC.COM](https://www.clickmechanic.com)